

## Clarke® Arc 131E 110 Volt 130 Amp Arc Welder

High Quality - Low Price

Operates from standard 110V circuit.

Variable amperage control for accurate welding power control.

Includes hand held face shield and chipping hammer.

Automatic thermal safety switch prevents overload.

Weld all carbon steel.

Uses 1/16" or 5/64" electrodes.

Simple to operate and portable.

Weight: 34 lbs

Working Range Amps: 40 - 100

Amps Peek: 130

Circuit Breaker Recommended: 25 amps

Input voltage / phase: 110 / single

Electrodes: 1/16" & 5/64"

Heat Settings: Variable

Duty Cycle: 30% at max output

Max Metal Thickness: 1/4"

10/2 - Year Limited Welder Warranty